THERMOSALD ISX - IPX A MODULAR SYSTEM FOR IMPULSE SEALING

NEW TECHNICAL FEATURES


THERMOREGULATOR CONFIGURABILITY LOW VOLTAGE SUPPLY PRECISION CALIBRATION PROBE WORKING VOLTAGES FROM 230 TO 600 VOLTS WORKING CURRENTS FROM 10 TO 500 AMPERE IP65 PANEL COPROCESSOR OPTION PROFIBUS OPTION AND OTHER FIELD BUSES ON-BOARD PLC OPTION WITH SEALING TIMES MAXIMUM TEMPERATURE ALARM PROBE CALIBRATING UP TO -30°C RAM DATA CHECK IN RUN TIME (v4.4)

OTHER FEATURES

COMPLETELY AUTOMATIC CALIBRATION ON-LINE THERMOREGULATOR SIZING BEST DIAGNOSTICS FOR TROUBLESHOOTING ALPHANUMERIC DISPLAY IN 6 LANGUAGES

COMPATIBILITY WITH ALL PREVIOUS MODELS





INSTALLATION AND USER MANUAL (V4)

3E S.r.l. - Via del Maccabreccia 37/a - 40012 LIPPO DI CALDERARA (BOLOGNA)

 Tel. ++39 051 6466225-228
 E-Mail: mail@3e3e3e.com

 Fax ++39 051 6426252
 Pagina web: www.3e3e3e.com

1 2		RODUCTION FETY INSTRUCTIONS AND CERTIFICATIONS	
	2.1	SAFETY INSTRUCTIONS	5
	2.2	COMPLIANCE WITH STANDARDS – CE MARKING	5
3	DES	SCRIPTION	.6
	3.1	INTRODUCTION ON THE MARKET	6
	3.2	DESCRIPTION OF THE PRODUCT AND ADVANTAGES	6
	3.3	OPERATING PRINCIPLE AND ADVANTAGES:	7
	3.4	APPLICATIONS	7
	3.5	CONFIGURABILITY AND ADVANTAGES	
4	INS	TALLATION	
	4.1	WARNINGS AND REQUIREMENTS FOR INSTALLATION	
	4.2	COMPONENT SELECTION AND TECHNICAL NOTES FOR INSTALLATION	11
	4.2.1 4.2.2		
	4.2.3	3 SIZING THE PROTECTION DEVICES	12
	4.2.4		
	4.2.5 4.2.6		
	4.2.7		
	4.3	WIRING DIAGRAMS	
	4.3.1 4.3.2		
	4.3.2 4.3.3		
	4.3.4	LOW COST WITH POTENTIOMETERS OR ANALOGUE OUTPUTS FROM PLC (THERMOSA	LD
	ISX1 4.3.5	I-IPX1 MODEL)	
	4.3.6	STANDARD WITH PROFIBUS / RS485 (THERMOSALD ISX2-IPX2 MODEL + OPERATO	OR
			20
	4.3.7 OPT	7 STANDÁRD WITH CAN BUS (THERMOSALD ISX2-IPX2 MODEL + OPERATOR PAN 10N)	
	4.3.8	STANDARD WITH PLC-ANALOGUE OPTION (THERMOSALD ISX2-IPX2 MODEL + OPERAT	OR
		EL OPTION)	
E		LIST OF EXCHANGE SIGNALS	
5			-
	5.1	COMMISSIONING WARNINGS	
	5.2	THERMOSALD ISX-LC – IPX-LC (LOW COST secondary - primary)	
	5.3	THERMOSALD ISX – IPX (STANDARD+ MULTILANGUAGE PANEL)	
	5.4	THERMOSALD ISX – IPX (+ ANALOGUE OPTION)	28
	5.5	INSTRUCTIONS FOR USING THE MULTILANGUAGE PANEL	
	5.5.1 5.5.2		
	5.5.3	3 Calibration Page	30
~		PARAMETERS Pages (structure and notes of the parameters contained in the submenus)	
6	MAI		
	6.1 mainter	REPLACING THE BAND WITH THE MACHINE COLD (i.e. bars at ambient temperature – schedu nance)	
T٢		SALD ISX – IPX – INSTALLATION AND USER MANUAL Rev.: 8	
Сс	ode: 3ES	S100_MDU_V4EN Page: 2 of: 56 Date: 08/07/2013	

	6.2 interver	REPLACING THE BAND WITH THE MACHINE HOT(i.e. bars at operating temperature - intion)	
	6.3	THERMOREGULATOR MAINTENANCE	33
7	6.4 TEC	GRIPPER JAWS MAINTENANCE	
	7.1	TECHNICAL DATA FOR THE MODULATION-ON-THE-SECONDARY MODEL	34
8	7.2 ORI	TECHNICAL DATA FOR THE MODULATION ON THE PRIMARY MODEL	
	8.1	CODES FOR ORDERING	35
	8.2	SUGGESTIONS FOR CHOOSING THE MODEL	37
	8.3	POSSIBLE CONFIGURATIONS	37
•	8.4		
		DIX A – SEALING CYCLE DIX B - MACHINE DATA LIST	
A	PPEND	DIX B1 – PRIORITY MACHINE DATA managed directly on the MAIN MENU	
		DIX C - SETTING DATA LIST	
		DIX C1 – PRIORITY SETTING DATA managed directly on the MAIN MENU DIX D – LIST OF ALARMS AND MESSAGES (CAUSES – REMEDIES)	
		DIX E – MECHANICAL DIMENSIONS	
		DIX F – TABLE OF BANDS	
Α	PPEND	DIX G – COMMISSIONING SHEET	56

1 INTRODUCTION

This manual is the only complete document concerning the product represented on the front page. It contains safety instructions, a description of the device and some of its possible applications, instructions for installing, commissioning, servicing and disposing of the product, the codes and some examples for placing orders.

This manual is referred to in all the documents that accompany the product and must be consulted before using the product described.

In particular, read the instructions related to safety, installation, commissioning, servicing and disposal before using the product.

REVISION OF THE MANUAL:

Rev.: 0	Data: 13/11/2010	Software V3.0
Rev.: 1	Data: 01/03/2011	
Rev.: 2	Data: 15/06/2011	Software V3.1
Rev.: 3	Data: 08/11/2011	Software V3.2, V3.3
Rev.: 4	Data: 19/12/2011	Software V4.0
Rev.: 5	Data: 19/06/2012	Software V4.2
Rev.: 6	Data: 26/11/2012	Software V4.3
Rev.: 7	Data: 25/03/2013	Software V4.4
Rev.: 8	Data: 07/08/2013	Software V4.5, V4.6

2 SAFETY INSTRUCTIONS AND CERTIFICATIONS

2.1 SAFETY INSTRUCTIONS

- A proper specific and technical knowledge is required to install, commission, service or use the product. Consult this "USER MANUAL" and follow the instructions contained herein in compliance with the SAFETY REGULATIONS.

- Improper use of the apparatus may result in dangerous conditions for the operator and things and people nearby.

- Do not use the equipment in an explosive atmosphere or with explosive material.

- Do not use the equipment with flammable material without first taking the necessary safety precautions.

- Install and use the thermoregulator only in industrial applications.

- Use bands or wires with an appropriate positive temperature coefficient

(>= 8 x 10E-4 , 800ppm/K).

- Do not change the temperature coefficient unless you have sufficient know how.

- Mechanically fix the thermoregulator to the plate using the fixing holes.

- Before connecting it to the mains, connect the ground protection conductor to the fixing bolt which is identified by a yellow-green PE indicator on the heat sink.

- Do not connect the power circuit of the thermoregulator when the machine's mechanical guards are open.

- Do not power the thermoregulator if the protective cover has been removed.

- After a MASTER RESET procedure has been performed, set the parameters correctly before using the equipment.

2.2 COMPLIANCE WITH STANDARDS – CE MARKING

The device complies with the fundamental requirements set forth in the following European Directives that apply to the product with reference to the harmonized standards below:

 89/336/EEC EMC Directive and subsequent amendments 92/31/ECC and 93/68/EEC
 CEI EN 55022 – Electromagnetic Compatibility (EMC) – Emission for industrial environments
 CEI EN 61000-6-2 – Electromagnetic Compatibility (EMC) – Part 6-2: Generic Standards -Immunity for industrial environments
 73/23/EEC /LOW VOLTAGE Directive and subsequent amendments 93/68/EEC
 CEI EN 60204-1 – Safety of machinery – Electrical equipment of machines Part 1: General requirements

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 5 of: 56

3 DESCRIPTION

3.1 INTRODUCTION ON THE MARKET

THERMOSALD ISX – IPX is a modular line of products that can be configured and are compatible with one another. This line has been designed to meet all demands in the IMPULSE SEALING market. THERMOSALD ISX – IPX springs from the company's long experience in the impulse sealing field and maintains total compatibility with all previous thermoregulators, namely THERMOSALD PWM, THERMOSALD SCR, THERMOSALD UPSCR and THERMOSALD ISC.

3.2 DESCRIPTION OF THE PRODUCT AND ADVANTAGES

Like the previous impulse thermoregulators, THERMOSALD ISX – IPX can quickly heat a sealing band or cutting/sealing wire to the set temperature without using additional probes. This technology makes it possible to obtain very high working speeds for sealing polyethylene, polypropylene, environment-friendly products and plastics in general.

The temperature is controlled directly on the sealing line and the temperature can be maintained even at high speeds. It avoids temperature drift between the first sealing operation and the next ones in production, it prevents the support bars from overheating, thus avoiding any subsequent mechanical problems caused by expansion. A cooling air blow and other precautions may further increase the speed and improve the sealing quality.

Below is a list of the most important functional-technical features of the new THERMOSALD ISX – IPX product in the following order: first the new features of this new model, than the features inherited from the previous ones.

- 24VNS insulated POWER SUPPLY: in the THERMOSALD ISX version with control on the secondary, it allows the same thermoregulator to be used regardless of the mains voltage.
- TEMPERATURE PROBE: it allows the band drift to be corrected over time
- POWER TRANSFORMER CONTROL ON THE SECONDARY OR PRIMARY: it allows the User to choose the best solution to the problem he/she has to solve within a voltage range of 230 to 600 Volts or current range of 150 to 400 Ampere.
- CONFIGURATION FREEDOM: it allows the user to choose the right model, from the less expensive one which is COMPLETELY ANALOGUE, to the most expensive and sophisticated model with COPROCESSOR and MODBUS RS485 FIELDBUS, PROFIBUS, CAN and others.
- IP65 OPERATOR PANEL:
- ON-BOARD PLC: it allows the thermoregulator to be used with times and internal logics for totally controlling small-sized semi-automatic sealing machines.
- COMPATIBILITY WITH ALL PREVIOUS THERMOREGULATORS: that allows spare parts to be replaced on obsolete models

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 6Page: 6of: 56

- Current sensor towards ground: to stop the machine in the case of an earth leak of the band to ground and subsequent sealing malfunction.
- COMPLETELY AUTOMATIC CALIBRATION: just press the calibration button to calibrate, without selectors or trimmers
- GUIDED SIZING OF THE POWER TRANSFORMER: the only sizing required is that of the power transformer which can be done with the aid of a guided menu on the display panel: the user enters the band data and the thermoregulator suggests the voltage, current and power of the transformer to be used
- ON-LINE ANALYSIS OF THE RESISTANCE, VOLTAGE AND CURRENT VALUES OF THE BAND: the equipment allows the theoretical, commissioning and run-time values of the resistance, voltage, current and power to be displayed and compared so as to help the operator troubleshoot any machine problems
- BEST DIAGNOSTICS FOR TROUBLESHOOTING: powerful diagnostics warns the user of any problem that has occurred on the machine, from a wiring mistake during installation to a failure problem during standard operation
- ALPHANUMERIC DISPLAY IN 6 LANGUAGES

3.3 OPERATING PRINCIPLE AND ADVANTAGES:

At all network cycles THERMOSALD ISX – IPX reads the voltage and current on the band, calculates the resistance and then the temperature, which depends on the resistance, and controls the current that heats the band in a closed loop; this current is generated by a power transformer by means of phase control performed on the secondary of the power transformer in the THERMOSALD ISX configuration and on the primary of the power transformer in the THERMOSALD IPX configuration: selection can be made according to machine requirements or company situations.

The new structure of the thermoregulator allows the user to operate without virtually having voltage or current limits as the problem shifts completely on to the power transformer and the system technical standards. For further information and details please refer to paragraph CONFIGURATIONS AND ADVANTAGES below.


3.4 APPLICATIONS

On all packaging machines that require polyethylene, polypropylene, environment-friendly and plastic films to be sealed or cut/sealed, vertical and horizontal filling machines, bundling machines, shoppers, vacuum machines, etc.


3.5 CONFIGURABILITY AND ADVANTAGES

The thermoregulator that best suits machine requirements can be built with the same basic dimensions, 120mm x 100mm.


MODEL	FEATURES	ADVANTAGES
	 completely analogue 	Low cost
THERMOSALD ISX - LC (LOW COST secondary)	 control on the secondary one model for all mains for output currents up to 250A 	- It can be used with other mains from 230V to 600V without changing the thermoregulator model
THERMOSALD IPX - LC (LOW COST primary)	 control on the primary change of model in case of 400V mains change for output currents up to 300A 	- Very high currents for very large bands



MODEL	FEATURES	ADVANTAGES
	120 x 100 H=130 -completely digital -precision sensor for zero point calibration -temperature sensor on power module	-Digital temperature settings -Powerful Diagnostics -Sealing parameter change -It allows the band drift to be compensated
THERMOSALD ISX + PANEL (standard secondary)	 control on the secondary one model for all mains for output currents up to 280-400A 	- It can be used with other mains from 230V to 600V without changing the thermoregulator model
THERMOSALD IPX + PANEL (standard primary)	 control on the primary change of model in case of 400V mains for output currents up to 400A 	- Possible implementations even with very high currents for very large bands



MODEL	FEATURES	ADVANTAGES
	120 x 100 H=170 -completely digital	-Digital temperature settings -Powerful Diagnostics
	-precision sensor for zero	-Sealing parameter change
	point calibration	-It allows the band drift to be
	-temperature sensor on	compensated
	power module – Coprocessor	Maximum flexibility
	Option -RS485 Modbus Option	
	-Profibus Option	
	-Can bus Option	
	-Analogue Option	
	-Sealing Times and PLC	
THERMOSALD ISX	Option	- It can be used with other
+ PANEL	- control on the secondary -one model for all mains	mains from 230V to 600V
+OPTIONS	- for output currents up to	without changing the
(secondary+options)	280-400A	thermoregulator model
THERMOSALD IPX	- control on the primary	- Possible implementations
+ PANEL	-change of model in case of	even with very high currents
+IPX OPTIONS	400V mains	for very large bands
(primary+options)	-for output currents up to 400A	



THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 10 of: 56

4 INSTALLATION

4.1 WARNINGS AND REQUIREMENTS FOR INSTALLATION

- BEFORE STARTING to INSTALL carefully read the SAFETY WARNINGS contained in this manual.

- This apparatus must be installed in accordance with the requirements set forth in standard CEI - EN60204

- This apparatus must be installed carefully following the instructions contained in this USER MANUAL

- This apparatus must be installed by skilled and properly trained personnel

4.2 COMPONENT SELECTION AND TECHNICAL NOTES FOR INSTALLATION

(Please refer to the diagrams under paragraph 4.3)

Below are the calculations to define the voltage and current required for the best application; select the suitable THERMOSALD ISX-IPX from the order table according to the values calculated.

4.2.1 SECONDARY/PRIMARY THERMOREGULATOR

- The apparatus must be installed inside an electrical panel, protected against dust, water and corrosive acids.

-The apparatus does not require special ventilation when used, but must be installed in a properly ventilated area; when the machine reaches steady-state operation, check that the heat sink of the thermoregulator does not exceed 60°C, if so, increase ventilation; a safety temperature probe is installed in models ISX2 and IPX2.

4.2.2 POWER TRANSFORMER AND SIZING

- A power transformer suitable for the circulating currents must be envisaged to supply power to the sealing band as indicated in the diagrams (ref. par. 4.3); in the case of a overlapped winding transformer, place a shield between the primary and secondary to avoid mains leaks on the secondary

-The power transformer can be sized simply using the thermoregulator's panel (diagnosis menu – see description in the commissioning section) or as follows: Calculate the band cross-section CROSS-SECTION[sq.mm] = WIDTH[mm] x THICKNESS[mm]

Calculate rated heating current Inom [A]= 30[A/sq.mm] x CROSS-SECTION[sq.mm] Calculate useful resistance Ru[ohm]=Specific resistance[ohm/m] x Useful length [m] Calculate the rated voltage and power

Vnom[V]= Ru[ohm] x Inom [A], Pnom= Vnom x Inom.

Follow the suggestions of the notes below:

NOTE1: maximum theoretical voltage VT and current IT of the transformer are calculated according to the machine's speed requirements: a coefficient x 1.5, x 2, i.e. VT=Vnom x coefficient, IT=Inom x coefficient, can be applied.

NOTE2: the maximum theoretical power of the transformer is calculated without considering the first full-wave heating impulses and according to a phase modulation mean factor, $PT = VT \times IT \times 0.7$

NOTE3: the actual mean power of the transformer depends on the number of sealing operations per minute, the ratio between the active state and sealing cycle period and the thickness of the film to be sealed; due to overall dimension reasons and costs, the PT theoretical power can be declassified introducing a SIF intermittent duty-type of the transformer (which, according to experience, should be about 50%-40%).

4.2.3 SIZING THE PROTECTION DEVICES

Envisage a D CURVE protection thermal magnetic circuit breaker to disconnect the mains as indicated in the diagrams (ref. par. 4.3).

Calculate the breaking current = theoretical heating current IT divided by secondary-primary coils ratio Q.

Ithermal magnetic circuit breaker = IT / Q

NOTE1: the value of the protection device of the power transformer's secondary must be the same as or higher than the calculated theoretical current IT; this protection device trips on the cables and band downstream of it. Considering that the thermoregulator is already fitted with an electronic protection device on the cables' and band's current, the fitter should analyze the possibility of not installing said protection device on the basis of the application.

NOTE2: please note that the suggested protection devices must be verified by the designer according to the application.

4.2.4 ELECTROMECHANICAL SYSTEM

-The safety chain must be made like the one in the base drawing (ref. par. 4.3). the emergency output contact must interrupt the power electromechanically; in particular, it must open the contactor necessary for interrupting the power transformer's power supply. this contact must be suitable for the circulating currents; this interruption is crucial because if the electronic switch inside the thermoregulator fails (very rare event), only the contactor can prevent the bands from overheating and breaking.

- Install an emergency button as indicated in the diagrams (ref. Par. 4.3). It must only be possible to reset this button manually and must be placed in a non-dangerous area that the operator can access easily.


4.2.5 MAINS FILTER

-No cases of interference with equipment nearby have occurred with THERMOSALD ISX, phase control on the secondary. The system designer has to decide whether or not one single filter should be fitted at the input of the system for the entire machine according to the emission measurements taken on the mains.


-A mains filter is recommended for THERMOSALD IPX, phase control on the secondary. The system designer has to decide whether or not one single filter should be fitted at the input of the system for the entire machine according to the emission measurements taken on the mains.

4.2.6 WIRING

SINGLE BAND CONNECTION



BAND CONNECTION IN PARALLEL



The apparatus must be installed inside an electrical panel, screwed on a iron plate zinc plated.

Warning: one end of the band's power circuit is connected to PE; this connection is made in the grey power terminal block CN1, terminals 2 and 3. Do not ground the band directly.

The transformer-thermoregulator cables must be twisted

The power cables to the band can be laid in a cable duct with other cables but must be twisted to avoid any interference. If other apparatus electrically much noise are in the plant (electric welders, brushless drivers, inverters), it's possibly increase noise immunity using use shielded cables in compliance with EMC requirements.

Cable cross-section 10 sq.mm for bands with a total cross-section ≤ 2.0 sq.mm (e.g. 2 bands in parallel 4 x 0.25)

16sq.mm for bands with a total cross-section >2.0sq.mm (e.g. 2 bands in parallel 6 x 0.3)

The reference cables must be shielded-twisted; for the best connection fix them directly on the terminals of a band. To increase the system's strength, and as our long experience has taught us, we recommend you to connect wire to a terminal near sealing bands as indicated in the adjacent drawings.

Set the wiring so as to obtain 1 independent box with the support terminal block for every thermoregulator so as to ensure that the cables of a thermoregulator do not get tangled with the cables of another thermoregulator or of another electrical noise units.

In compliance with EMC requirements MAINS FILTER is not necessary on the application

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage:13of:56

with control on the secondary

4.2.7 INSTALLATION

Electrically disconnect the electrical panel and make sure no voltage is being supplied to the mains connection terminals.

Screw the thermoregulator on the bottom of the electrical panel.

Connect the ground wire (with the same cross-section as the power cables) to the thermoregulator's PE bolt.


Wire the power cables as described previously.

Wire the reference cables as described previously.

Perform the safety chain as described previously.

4.3 WIRING DIAGRAMS


4.3.1 DIGITAL SIGNAL CONNECTIONS



CONSTRUCTION NOTES:

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 15 of: 56

4.3.2 CONTROL ON THE SECONDARY – POWER CONNECTIONS (THERMOSALD ISX MODEL)




TECHNICAL NOTES:

In observance to the EMC norme the main filter cannot be used. In the case of the COPROCESSOR OPTION connector CN6 – References and the current transformer (CT) are doubled.

CONSTRUCTION NOTES:

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage:16of:56

4.3.3 CONTROL ON THE PRIMARY – POWER CONNECTIONS (THERMOSALD IPX MODEL)




TECHNICAL NOTES:

In the case of the COPROCESSOR OPTION connector CN6 – References and the current transformer (CT) are doubled.


CONSTRUCTION NOTES:

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 17 of: 56

4.3.4 LOW COST WITH POTENTIOMETERS OR ANALOGUE OUTPUTS FROM PLC (THERMOSALD ISX1-IPX1 MODEL)




THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage:18of:56




4.3.5 STANDARD WITH OPERATOR PANEL (THERMOSALD ISX2-IPX2 MODEL)

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 19 of: 56


4.3.6 STANDARD WITH PROFIBUS / RS485 (THERMOSALD ISX2-IPX2 MODEL + OPERATOR PANEL OPTION)



4.3.7 STANDARD WITH CAN BUS (THERMOSALD ISX2-IPX2 MODEL + OPERATOR PANEL OPTION)



4.3.8 STANDARD WITH PLC-ANALOGUE OPTION (THERMOSALD ISX2-IPX2 MODEL + OPERATOR PANEL OPTION)



THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage:22of:56

4.4 LIST OF EXCHANGE SIGNALS

This list specifies the list of the connections and related PINS of

CN1 – POWER TERMINAL BLOCK (MODEL WITH CONTROL ON THE SECONDARY)

PIN1	ALTERNATING POWER SUPPLY
PIN2	ALTERNATING POWER SUPPLY
PIN3	BAND -
PIN4	BAND +

NOTE1: We recommend you twist the power cables

CN1 – POWER TERMINAL BLOCK (MODEL WITH CONTROL ON THE PRIMARY)

PIN1	ALTERNATING POWER SUPPLY INPUT (230VAC)		
PIN2			
PIN3	CONNECT TO 0V OF THE POWER SECONDARY TO CHECK GROUND CURRENT		
PIN4	PHASED POWER SUPPLY OUTPUT TO THE PRIMARY OF TRANSFORMER		

NOTE1: We recommend you twist the power cables

NOTE2: Alternating supply of the control circuit with the same phase as that of the power circuit

CN2 – CONTROL CIRCUIT POWER SUPPLY TERMINAL BLOCK

PIN 1	0 Vdc	(max absorption: 0.5 A)
PIN 2	24 Vdc	(max absorption: 0.5 A)

NOTE1: 0-24VDC is insulated from the internal power supply and ground

CN3 – COMMAND TERMINAL BLOCK

PIN1	0 V PLC COMMON (24 Vdc)	(max absorption: 0.1 A)
PIN2	PREHEATING COMMAND FROM 24 Vdc PLC (0)	(20 mA max)
PIN3	SEALING COMMAND FROM 24 Vdc PLC (0)	(20 mA max)
PIN4	RESET COMMAND FROM 24 Vdc PLC (0) DC	(20 mA max)
PIN5	CALIBRATION COMMAND FROM 24 Vdc PLC (0) DC	(20 mA max)
PIN6	SEALING ALARM (N.C. CONTACT)	(4 A max)
PIN7	SEALING ALARM (N.C. CONTACT)	(4 A max)

CN4 – CONNECTOR FOR DISPLAY PANEL (15 POLES, FEMALE)

-		
PIN1	+5 Vdc	Shielded (0.25 sq.mm)
PIN2	0 V	Shielded (0.25 sq.mm)
PIN3	SPI-SDO	Shielded (0.25 sq.mm)
PIN4	SPI-SCK	Shielded (0.25 sq.mm)
PIN5	SPI-SDI	Shielded (0.25 sq.mm)
PIN6		
PIN7		
PIN8		
PIN9	SPI-SS	Shielded (0.25 sq.mm)
PIN10	DO NOT USE	Shielded (0.25 sq.mm)
PIN11	DO NOT USE	Shielded (0.25 sq.mm)

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage:23of:56

PIN12	DO NOT USE	Shielded (0.25 sq.mm)
PIN13	DO NOT USE	Shielded (0.25 sq.mm)
PIN14		
PIN15		

NOTE1: The thermoregulator-panel connection cable must be shielded with pin-to-pin connection. Max 15 m.

CN5 – PHASE INPUT TERMINAL BLOCK FOR SYNCHRONISM

PIN1	230-480 VAC MAIN NET SYNCRONISM (10ma max)
PIN2	0 VAC (10ma max)

CN6 – REFERENCE TERMINAL BLOCK

PIN1	REF- BAND REFERENCE	(1 mA max)
PIN2	REF+ BAND REFERENCE	(1 mA max)
PIN3	REF0 REFERENCE CABLE SHIELD (do not connect on	
	the machine side)	
PIN4	CT- REFERENCE	(500 mA max) twisted
		cable
PIN5	CT+ REFERENCE	(500 mA max) twisted
		cable
PIN6	REF0 REFERENCE CABLE SHIELD (do not connect on	
	the machine side)	

CN7 - POTENTIOMETER CONNECTOR (9 POLES, MALE)

PIN1	+4.5V PREHEAT POTENTIOMETER 10Kohm	(1 mA max)
PIN2	REF+ PREHEAT POTENTIOMETER 10Kohm	(1 mA max)
PIN3	0V PREHEAT POTENTIOMETER 10Kohm	(1 mA max)
PIN4	jumper PIN3 and PIN4	(1 mA max)
PIN5		
PIN6	+4.5V SEALING POTENTIOMETER 10Kohm	(1 mA max)
PIN7	REF+ SEALING POTENTIOMETER 10Kohm	(1 mA max)
PIN8	0V SEALING POTENTIOMETER 10Kohm	(1 mA max)
PIN9	jumper PIN8 and PIN9	(1 mA max)

NOTE1: if piloted from analogue PLC output, use PIN2,PIN3,PIN7,PIN8 and leave PIN4-PIN9 free.

NOTE2: REF-, REF+: we recommend you use a shielded twisted pair (e.g. TWINAX IBM cable, our code 3esd0066)

CN8 – ANALOGUE OUTPUT TERMINAL BLOCK

PIN 1	0 Vdc ANALOGUE	(5ma max)
PIN 2	0-5 Vdc ANALOGUE REFERENCE OUTPUT	(5ma max)
PIN 3	ANALOGUE REFERENCE OUTPUT CABLE SHIELD	

CN9 – TEMPERATURE PROBE CONNECTOR (9 POLES, FEMALE)

PIN1	OV	(1 mA max)	
PIN2	+5 Vdc	(1 mA max)	
PIN3			

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 24 of: 56

PIN4		
PIN5		
PIN6		
PIN7	OUT CLOCK	(1 mA max)
PIN8		
PIN9	DATA	(1 mA max)

CN10 - PROFIBUS / 485 SERIAL CONNECTOR (9 POLES, FEMALE)

PIN1	
PIN2	
PIN3	Profibus B / Rs485 A+
PIN4	Rs485 Enable
PIN5	
PIN6	
PIN7	
PIN8	Profibus A / Rs485 B-
PIN9	

NOTE1: we recommend you use a shielded cable

CN11 – CAN BUS TERMINAL BLOCK

PIN1	CAN – V-
PIN2	CAN L
PIN3	0 V EXTERNAL (INSULATED)
PIN4	CAN H
PIN5	CAN – V+

CN12 – ANPLC TERMINAL BLOCK

BULL		
PIN1	0 V COMMON	
PIN2	IN0 Closed bar	(10 mA max)
PIN3	IN1	(10 mA max)
PIN4	IN2	(10 mA max)
PIN5	IN3	(10 mA max)
PIN6	IN4	(10 mA max)
PIN7	IN5	(10 mA max)
PIN8	IN6	(10 mA max)
PIN9	IN7	(10 mA max)
PIN10	24 Vdc COMMON	
PIN11	OUT0 CLOSED BAR	(0-500 ma)
PIN12	OUT1 BLOW	(0-500 ma)
PIN13	OUT2	(0-500 ma)
PIN14	OUT3	(0-500 ma)

5 <u>COMMISSIONING</u>

5.1 COMMISSIONING WARNINGS


-BEFORE STARTING COMMISSIONING carefully read the SAFETY WARNINGS and INSTALLATION WARNINGS in the USER AND INSTALLATION MANUAL this chapter is an integral part of or a copy of it.

-The system must have been sized as specified in the installation warnings and built in a workmanlike fashion.

-The thermoregulator is provided in the MASTER RESET condition. After every MASTER RESET the parameters return to the default status: if they were changed for operation purposes, the working parameters are to be set; in this case 4 leds on the equipment in the right are blinking.

-For any further information do not hesitate to contact 3E.

5.2 THERMOSALD ISX-LC – IPX-LC (LOW COST secondary - primary)



Step 1 – calibrate only after reading the commissioning warnings.

Step 2 - the machine must be at ambient temperature

Step 3 – the preheat and sealing commands must be deactivated

Step 4 – power the thermoregulator

Step 5 – in the event of an alarm, red ALARM LED on, follow the thermoregulator's suggestions and solve (the alarm number can be identified by counting the impulses of the green balance LED for tens – e.g. 9 impulses = 90 - + the impulses of the red balance LED for units – e.g. 10 impulses = 0).

Point 6 - calibrate: press the external CALIBRATION button and wait (the 2 LEDs on the equipment blink during calibration)


Step 7 – at the end of calibration the machine is ready to work: set the preheat and sealing temperature on the preheat and sealing potentiometers (30 degrees/turn)

NOTE 1: if calibration problems occur, perform a MASTER RESET and proceed from step 2 (to perform the MASTER RESET: keep the external RESET + CALIBRATION button pressed for 6 seconds; the 4 LEDs on the equipment remain on for 3 seconds).

NOTE 2: set the preheat and sealing temperatures with 2 potentiometers 10Kohm (30 degrees/turn) or with analogue plc outputs ($13mV/degree - 13mv \times 300^{\circ}C = 3.9V$, 4.2V alarm, range 0-5V).

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 26 of: 56

5.3 THERMOSALD ISX – IPX (STANDARD+ MULTILANGUAGE PANEL)



Step 1 – calibrate only after reading the commissioning warnings.

Step 2 - the machine must be at ambient temperature

Step 3 – the preheat and sealing commands must be deactivated

Step 4 – power the thermoregulator

Step 5 - in the event of an alarm, thermoregulator's red ALARM LED on, follow the panel's suggestions and solve (the alarm number and the description in the language selected among the 6 possible ones)

Point 6 - calibrate: keep the green CAL button on the multilanguage panel pressed for 3 seconds (the 2 LEDs on the equipment blink during calibration).

Step 7 – at the end of calibration the machine is ready to work; set the preheat and sealing temperature in the TEMPERATURE submenu as specified in paragraph 5.5.4.

Step 8 – Press the RES button and follow the instructions to go back to the homepage

NOTE 1: for the next calibrations press the CAL+MODE+CAL buttons on the multilanguage panel in sequence (see par. 5.5.3 Calibration Page)


NOTE 2: calibration can also be performed from outside, as described in paragraph 5.2 of the LOW COST configuration.

NOTE 3: if calibration problems occurs, perform a MASTER RESET according to one of the following procedures:

procedure 1 - Keep ARROW DOWN + ARROW UP on the multilanguage panel pressed for 6 seconds.

procedure 2 – Keep the external RESET + CALIBRATION buttons pressed at the same time for 6 seconds

The 4 LEDs on the equipment remain on for 3 seconds during the MASTER RESET.



5.4 THERMOSALD ISX – IPX (+ ANALOGUE OPTION)

NOTE 1: set the CONFIGURATION MACHINE DATA=1 potentiometers+display to enable the potentiometers.

NOTE 2: set the maximum preheat and sealing temperatures on the panel and decrease them with the analogue inputs (with 2 potentiometers 10Kohm (30 degrees/turn) or with analog plc output ($13mV/degree - 13mv \times 300^{\circ}C = 3.9V$, 4.2V alarm, range 0-5V)).

NOTE 3: please refer to paragraph 5.3 for the other functions.

5.5 INSTRUCTIONS FOR USING THE MULTILANGUAGE PANEL


NOTE: It is possible to go back to the homepage from any page by pressing the RES button repeatedly.

NOTE: Press the MODE button to access the LEVEL 2 submenu pages and then the ARROW DOWN ▼ and ARROW UP ▲ buttons.

NOTE: Any parameter displayed can be changed as follows: Press the MODE button to access the change status: "? 080" Press the ARROW UP button to change the data: "? 081" Press the MODE button to exit the change status: "= 081"

NOTE: Confirmation is requested before saving a change to any parameter: ???CONFIRMATION???? YES=MODE NO=RES Answer YES to confirm, NO to reset the previous data.

5.5.1 Homepage – (WARN 33 shows that there is no power on the input terminals)




To perform a **MASTER RESET** keep the arrow up and arrow down button pressed for 6 seconds until figure 5.4.2 is displayed

To **CALIBRATE** press the **CAL + MODE + CAL** button as shown in figure 5.4.3.

For any **PARAMETER** access the submenu and search for the parameter to be changed as indicated in the table under paragraph 5.4.4.

5.5.2 Master Reset Page



Using the Master Reset procedure the thermoregulator self-configures according to the hardware installed. The parameters are initialized as factory set: if a parameter has been changed, it must be returned to the working condition.

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage:29of:56

5.5.3 Calibration Page



Press MODE to access the calibration page

Press the $\ensuremath{\text{CAL}}$ button to start calibration



5.5.4 **PARAMETERS** Pages (structure and notes of the parameters contained in the submenus)

Note: the parameters that are changed most frequently are indicated in red

TEMPERATURES	(see appendix C1)
PREHEAT TEMP.	We recommend you set it to 40° less than the sealing temp.
SEALING TEMP.	Sealing temperature
INCREASE SEALING	Increase of sealing temperature for band compensation
INCREASE NR	Number of sealing for increasing temperature
RECOVERY TIME	Time tor resetting initial temperature
BALANCE TEMPERATURE	
THEORET. CALCULATIONS	
BAND WIDTH	Theoretical value to size the machine - not required for operation.
BAND THICKNESS	Theoretical value to size the machine - not required for operation.
WIRE DIAMETER	Theoretical value to size the machine - not required for operation.
BAND LENGTH	Theoretical value to size the machine - not required for operation.
NO. IN PARALLEL	Theoretical value to size the machine - not required for operation.
NO. IN SERIES	Theoretical value to size the machine - not required for operation.
OHM for SQ.MM / M	Theoretical value to size the machine - not required for operation.
AMPERE FOR SQ.MM	Theoretical value to size the machine - not required for operation.
DUTY CYCLE	Theoretical value to size the machine - not required for operation.
TECHNICAL ANALYSIS	
IMAX	Maximum RMS current (typical data of the thermoregulator model)
I2T	Integral current per time unit
1	Heating RMS current
THEORETICAL R	Theoretical resistance of the band (resulting from theoretical calculations)
R0	Calibration Resistance
R	RunTime Resistance
THEORETICAL I	Theoretical full-wave RMS current of the band (from theoretical calculations)
THERMOSALD ISX - IPX - IN	STALLATION AND USER MANUAL Rev.: 8

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 30 of: 56

10	Calibration full-wave RMS current
10	RunTime full-wave RMS current
THEORETICAL V	
	Theoretical full-wave RMS voltage of the band (from theoretical calculations)
VO	Calibration full-wave RMS voltage
V	RunTime full-wave voltage
THEORETICAL P	Theoretical full-wave power of the band Vx I x0.7(from theoretical calculations)
P0	Calibration full-wave RMS power V x I x 0.7
P	RunTime full-wave RMS power V x I x 0.7
RATING WORKING	Rating working 0-100% (100% works not in protection - best running). The
	data is updated any 10 seconds)
TEMP SENSOR ON	ON= precision sensor enabled
ACT. 1	ON= precision sensor active
TEMP	Precision Sensor Temperature
COMMANDS	
PREHEAT CMD	Manual control from the keyboard
SEALING CMD	Manual control from the keyboard
BURN IN CMD	Manual control from the keyboard
CMD IN CURRENT	Manual control from the keyboard
EMERGENCY TEST	
EMERGENCY TEST	Press the MODE button to check the emergency chain
SAVE CALIBRATION DATA	
SAVE CAL. DATA	Press the MODE button to save the data of the last calibration
CONFIGURATION MODE	
CONFIGURATION MODE	0=impulse sealing
TEMP.COEFF.(PPM)	
TEMP.COEFF.(PPM)	It is modified to adjust the thermoregulator to the material of the sealing band
CONFIGURATION	0=Impulse sealing (preset for extensions-do not change)
RESOLUTION	System resolution in bit/degree
MAX SEAL. TEMPERATURE	
MAX SEAL. TEMP.	It is modified to change the band's working temperature limits
I2Tx1SEC	
I2Tx1SEC	Maximum rms current for 1 second
FIELD BUS	
FIELD BUS	Parameters for the RS485 Modbus or other Field Bus
SETTING DATA	
LANGUAGE SELECT.	Italian, English, French, German, Spanish, to be defined
DISPLAY DEGREES	see Appendix C, Setting Data List
MAX SEAL. TEMP.	see Appendix C, Setting Data List
G/SEC GRADIENT	see Appendix C, Setting Data List
GROUND CURRENT	see Appendix C, Setting Data List
WARN66 TIME	see Appendix C, Setting Data List
SET PAGE1 TEMP.	see Appendix C, Setting Data List
MACHINE DATA	
RATED I	see Appendix B, Machine Data List
	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP	see Appendix B, Machine Data List
RATED I	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV	see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI	see Appendix B, Machine Data List see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI	see Appendix B, Machine Data List see Appendix B, Machine Data List see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI INT. THRESHOLD IN INT. THRESHOLD FS	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI INT. THRESHOLD IN INT. THRESHOLD FS	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI INT. THRESHOLD IN INT. THRESHOLD FS DERIVATIVE GAIN KD READ DELAY	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI INT. THRESHOLD IN INT. THRESHOLD FS DERIVATIVE GAIN KD READ DELAY PARTIAL SHORT	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI INT. THRESHOLD IN INT. THRESHOLD FS DERIVATIVE GAIN KD READ DELAY	see Appendix B, Machine Data List see Appendix B, Machine Data List
RATED I RAMP PROP. G. KV INTEGRAL GAIN KI INT. THRESHOLD FI INT. THRESHOLD IN INT. THRESHOLD FS DERIVATIVE GAIN KD READ DELAY PARTIAL SHORT CIRCUIT FACTOR	see Appendix B, Machine Data List see Appendix B, Machine Data List

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 31 of: 56Date: 08/07/2013

CONFIGURATION DISPLAY	see Appendix B, Machine Data List
PLC OPTION	see Appendix B, Machine Data List
TEMP SENSOR ENABL.	see Appendix B, Machine Data List
PASSWORD 1=P/2=T	see Appendix B, Machine Data List
KEY PASSWORD	see Appendix B, Machine Data List
INFORMATION	
3E s.r.l. – BO – ITALY	
CUSTOMER CARE	mail@3e3e3e.com
THERMOREG.MODEL	THERMOSALD ISX / IPX
THERMOREG.VERSION	Thermoregulator Software Release
DISPLAY VERSION	Panel Software Release

6 MAINTENANCE

6.1 REPLACING THE BAND WITH THE MACHINE COLD (i.e. bars at ambient temperature – scheduled maintenance)

1 – Power off, remove the preheat and sealing commands, let the gripper jaws cool down.

2 – Mount the new bands.

3 – Power on.

4 – Calibrate in order to compensate for any minor mechanical differences of the band (in most cases ambient temperature does not need to be changed in the setting data). 5 – THE MACHINE is ready to work.

6.2 **REPLACING THE BAND WITH THE MACHINE** HOT(i.e. bars at operating temperature - quick intervention)

1 – Power off, remove the preheat and sealing commands, let the gripper jaws cool down so the operator can work comfortably.

2 - Mount the new bands.

3 – Power on.

4 – If there are no great mechanical differences in the bands THE MACHINE is ready to work.

6.3 THERMOREGULATOR MAINTENANCE

To be scheduled according to the work environment, in any case with routine maintenance intervals should be no longer than 180 days.

1 – Make sure the connection terminals are properly screwed.

2 – Periodically check correct operation of the output safety alarm contact (press the mode button as requested at start-up to check the alarm circuit: the emergency output relay must open and the power circuit must remain disconnected).

6.4 GRIPPER JAWS MAINTENANCE

To be scheduled according to the work environment at periodic intervals.

1 – Make sure the feedback reference terminals and power terminals are properly screwed.

2 – Make sure the band's terminals are highly conductive and do not show any oxidation or bad contacts: if so, service them accurately.

3 – Check the band's supports in insulating material and Teflon.

7 TECHNICAL DATA

7.1 TECHNICAL DATA FOR THE MODULATION-ON-THE-SECONDARY MODEL

24VDC +/- 20% (max absorption: 0.2 A)	
SECONDARY POWER TRANSFORMER	
300 Ampere	
50 – 60 Hz automatic switchover	
24 VDC (max absorption: 20 ma)	
250 V 4 A	
0.3 degree	
≅ +/- 1°C	
Depend of the thermic drift of sealing band	
Can be set on the display panel 0-300°C	
Can be set on the display pannel 0-300°C	
External by PLC	
-40°C + 50°C	
IP00	
kg 1.6	

7.2 TECHNICAL DATA FOR THE MODULATION ON THE PRIMARY MODEL

CONTROL POWER SUPPLY (CN2)	24VDC +/- 20% (max absorption: 0.2 A)
POWER SUPPLY	230-480VAC
SHORT CIRCUIT CURRENT	300 Ampere
MAINS FREQUENCY	50 – 60 Hz automatic switchover
DIGITAL COMMANDS	24 VDC (max absorption: 20 ma)
SEALING ALARM CONTACT	250 V 4 A
REPETITIVENESS	≅ +/- 1°C
PREHEATING TEMPERATURE	Can be set on the display pannel 0-300°C
SEALING TEMPERATURE	Can be set on the display pannel 0-300°C
SEALING AND COOLING-DOWN TIME	External by PLC
WORKING ENVIRONMENT TEMPERAT.	-40°C + 50°C
THERMOREGULATOR PROTECTION	IP00
RATING	
POWER UNIT WEIGHT	kg 1.6

8 ORDERING DATA

8.1 CODES FOR ORDERING

MODELS	Description	ORDERING CODE
THERMOSALD ISX-60A-3L	Impulse thermoregulator - standard	3ES103S6
	SECONDARY - 60 Ampere (3 levels)	
THERMOSALD ISX-90A-3L	Impulse thermoregulator - Standard	3ES103S9
	SECONDARY - 90 Ampere (3 levels)	
THERMOSALD ISX-60A-4L	Impulse thermoregulator - Standard	3ES104S6
	SECONDARY - 60 Ampere (4 levels)	
THERMOSALD ISX-90A-4L	Impulse thermoregulator - Standard	3ES104S9
	SECONDARY - 90 Ampere (4 levels)	
THERMOSALD ISX-60A-5L	Impulse thermoregulator - Standard	3ES105S6
	SECONDARY - 60 Ampere (5 levels)	
THERMOSALD ISX-90A-5L	Impulse thermoregulator - Standard	3ES105S9
	SECONDARY - 90 Ampere (5 levels)	
		05040004
THERMOSALD IPX-400V-3L	Impulse thermoregulator - standard	3ES103P4
THERMOSALD IPX-400V-4L	PRIMARY - 400-480V (3 levels) Impulse thermoregulator - standard	3ES104P4
THERMOSALD IPX-4000-4L	PRIMARY - 400-480V (4 levels)	3E5104P4
THERMOSALD IPX-400V-5L	Impulse thermoregulator - standard	3ES105P4
THERINOSAED IF X-400V-SE	PRIMARY - 400-480V (5 levels)	3L310JF4
Precision Sensor Option	Bar temperature checking probe	Z=PROBE
	(+0 Levels)	
High Volt Option	Voltage on band: 100-140V(+0 Levels)	3ES100Z=HV
Low Volt Option	Voltage on band: 3-10V(+0 Levels)	3ES100Z=LV
Coprocessor Option	Coprocessor (+1 Levels)	3ES100Z=COPRO
Analogue Option	Analogue inputs + 1 output (+1 Levels)	3ES100Z=AN
PLC Option	PLC+ Times (+1 Levels)	3ES100Z=PLC
Analogue+PLC Option	PLC+ Times+Analogue inputs (+1 Levels)	3ES100Z=ANPLC
RS485 Option	RS485 MODBUS Field bus (+1 Lev.)	3ES100Z=RS485
Profibus Option	PROFIBUS Field bus (+1 Levels)	3ES100Z=PROFI
Can bus Option	CAN Field bus (+1 Levels)	3ES100Z=CAN
Multilanguage Panel	Digital multilanguage panel for thermosald	3ES108
IP65 Option	IP65 protection (verify drilling template)	3ES108Z=IP65
Pan-rs485 Option	RS485 (being developed)	3ES108Z=RS485
Pan-adapter frame Option	Adjusting frame with UPSCR model	3ES108Z=COADA
Precision Sensor	External temperature sensor	3ES109B1
CABLE	Panel-thermoregulator connection cable,	3ES080A001/1
	1 m	
CABLE	Panel-thermoregulator connection cable,	3ES080A001/3
	3 m	

THERMOSALD ISX – IPX – INSTALLATION AND USER MANUAL Code: 3ES100_MDU_V4EN Page: 35 of: 56

CABLE	Panel-thermoregulator connection cable, 5 m	3ES080A001/5
ТА	Current transformer	3ES080A002
Power transformer	Contact technical department for sizing	

Bands, Belts and sealing wires	Bands, belts and sealing wires with different profiles, in metres, specifically designed, copper-plated, Teflon-coated	
Installation and user manual V4 ITALIAN		3ES100_MDU_V4IT
Installation and user manual V4 ENGLISH		3ES100_MDU_V4EN
Installation and user manual software V4 FRENCH (not ready)		3ES100_MDU_V4FR
Installation and user manual software V4 GERMAN (not ready)		3ES100_MDU_V4DE
Installation and user manual software V4 SPANISH (not ready)		3ES100_MDU_V4SP
RS485 manual in ITALIAN		3ES100_485_IT
Profibus manual in ITALIAN		3ES100_PRO_IT
Can Bus Manual in ITALIAN (not ready)		3ES100_CAN_IT

8.2 SUGGESTIONS FOR CHOOSING THE MODEL

- Use model I=60A for a total band cross-section <= 2sq.mm
- Use model I=90A for a total band cross-section > 2sq.mm
- Use model HV for transformer V voltage > 100Vac)
- Use model LV for transformer V voltage < 10Vac
- All the options can be applied to standard models ISX2 and IPX2

8.3 POSSIBLE CONFIGURATIONS

- 3-LEVEL STRUCTURE All basic models
- 4-LEVEL STRUCTURE RS485 / PROFI / CAN Option
- 5-LEVEL STRUCTURE Options

ÁN / PLC / ANPLC / COPRO AN+COPRO / PLC+COPRO / ANPLC+COPRO RS485+COPRO / RS485+AN / RS485+PLC / RS485+ANPLC PROFI+COPRO / PROFI+AN / PROFI+PLC / PROFI+ANPLC CAN+COPRO / CAN+AN / CAN+PLC / CAN +ANPLC

8.4 ORDER EXAMPLES


PRODUCT NAME	ORDERING CODE
(order for thermoregulator, standard, second. 60A – 3	
Levels)	3ES103S6
THERMOSALD ISX-60A	
(order for multilanguage panel)	
Multilanguage Panel	3ES108
(order for thermoregulator, standard, secondary 90A – 5	
Levels)	
+ Profibus Option, 1 Level	
+ Coprocessor Option, 1 Level / Total of 5 Levels)	3ES105S9
THERMOSALD ISX-90A-5L	
Profibus Option	3ES100Z=PROFI
Coprocessor Option	3ES100Z=COPRO
(order for thermoregulator, standard, secondary 90A – 4	
Levels)	
+ Analogue+PLC Option, 1 Level / Total of 4 Levels	
+ Panel + User Manual in Italian)	3ES104S9
THERMOSALD ISX-90A-4L	
Analogue+PLC Option	3ES100Z=ANPLC
Multilanguage Panel	3ES108
Installation and user manual software V3 ITALIAN	3ES100_MDU_V3IT

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 37 of: 56

(order for thermoregulator, standard, primary 400V + Analogue Option, 1 Level	
+ Coprocessor Option, 1 Level / Total of 5 Levels	
+ Multilanguage Panel + User Manual in English)	
THERMOSALD IPX-400V-5L	3ES105P4
Coprocessor Option	3ES100Z=COPRO
Analogue Option	3ES100Z=AN
Multilanguage Panel	3ES108
Installation and user manual software V3 ENGLISH	3ES100_MDU_V3EN

APPENDIX A – SEALING CYCLE

NOTE - The sealing cycle suggested is given by way of example only and is not to be considered as a binding usage diagram. Experience shows that the timing must be changed according to the specific application, i.e. of the materials, dimensions, times, etc. For further information please contact our technical department.



APPENDIX B - MACHINE DATA LIST

NOTE – The machine data must be changed only by skilled and qualified personnel after contacting our technical department	
TO ACCESS: press the MODE button on the MACHINE DATA submenu TO EXIT: press the RES button	
RATED I = 60 / 90 / 120 (AMPERE)	
Cannot be changed, it shows the rated current of the model used	
HEATING RAMP = (U.M. = degrees/100ms, default = 40)	
Temperature increase rate following a preheat or sealing command [U.M. : degrees/100 ms]. Increasing this parameter means decreasing the time required to bring the band to the proper temperature, subsequently increasing speed, reducing stability, decreasing band life.	
PROPORTIONAL GAIN KV = (U.M., default = 100)	
Proportional loop gain. Increasing this parameter means increasing the loop reply speed and therefore making the system more ready.	
Increasing it too much may result in system instability and subsequently in temperature	
oscillation.	
INTEGRAL GAIN KI = (U.M., default = 40)	
Integral loop gain. Increasing this parameter means increasing temperature accuracy and the speed for achieving the temperature desired. Increase this parameter to increase system	
stability.	
Increasing it too much may result in a temperature overflow subsquent to a preheat or	
sealing command.	
INTEGRAL THRESHOLD LIMIT FI= (default = 60%) (soft.v4.4)	
It limits the maximum value of the integrative component in heat zone: increasing this value it	
increases the hot overshoot (contact our technical office)	
INTEGRAL THRESHOLD LIMIT IN= (default = 0%) (soft.v4.4)	
It limits the maximum value of the integrative component in cold zone: increasing this value it	
increases the speed of heating (contact our technical office)	
INTEGRAL THRESHOLD LIMIT FS= (default = 80%) (soft.v4.4)	
It limits the maximum value of the integrative component in production: increasing this value	
it increases the temperature of the bar in production (contact our technical office)	
DERIVATIVE GAIN KD = (U.M., default = 30)	
Derivative loop gain. Increasing this parameter means increasing the loop reply speed and	
therefore making the system more ready to changes.	
Increasing it too much may result in system instability and subsequently in temperature	
oscillation.	
READ DELAY = (default = 1200usec.) (soft.v4.4)	
It can modify the time of reading the analog converter; modifying this parameter help to	
improve the performance of the thermoregulator when an undersize power transformer is	
used(contact our technical office)	
PARTIAL SHORT CIRCUIT FACTOR = (U.M. , default = 1.2)	
It allows an instantaneous current threshold to be established, due to a partial short circuit,	
above which the thermoregulator goes in alarm condition F097.	
ALARM DISABLING1 = 0 (U.M.)	
THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 40 of: 56Date: 08/07/2013	

It allows any alarm to be disabled. To be used carefully. In certain cases it may allow the production cycle to restart. Alarm disabling must be considered temporary and actions must be taken immediately to remove its causes.

ALARM DISABLING2 = 0 (U.M.)

It allows any alarm to be disabled. To be used carefully. In certain cases it may allow the production cycle to restart. Alarm disabling must be considered provisional and actions must be taken immediately to remove its causes.

DISPLAY CONFIGURATION = 2

1=operation with potentiometers: the temperature set on the display can be limited by the analogue input.

2=operation with display only or FIELD BUS

PLC OPTION (default = OFF)

It is put to ON when the PLC card is plugged in, for managing sealing gripper jaw movement and sealing times

TEMPERATURE SENSOR ENABLING (ON/OFF)

It is automatically acquired during the MASTER RESET

PASSWORD ENABLING = 0

1=partial password; 2=total password

KEY PASSWORD (default = 0000)

Another password can be entered to block the data

<u>APPENDIX B1 – PRIORITY MACHINE DATA managed directly on the MAIN MENU</u> (see par.5.5.4 parameters pages)

BALANCE TEMPERATURE (default = 30)

It can be changed according to the ambient temperature during calibration; with the PRECISION SENSOR option this parameter is changed automatically at the end of a calibration procedure

TEMPERATURE COEFFICIENT (ppm – parts per million, default =1210)

It allows the thermoregulator to be adjusted to the type of band used. See safety standards in this manual. The value required is to be set again after a MASTER RESET.

CONFIGURATION MODE (default =0)

0=standard impulse sealing: control loop much reliable, fits perfectly to the machine conditions.

MAX Sealing TEMPERATURE (default = 250)

It can be changed according to the maximum temperature allowed. The value required is to be set again after a MASTER RESET.

I2T for 1 SECOND (default = 200 Ampere)

It can be decreased according to the protection rating desired on the machine

APPENDIX C - SETTING DATA LIST

NOTE – The machine data must be changed only by skilled and gualified personnel after contacting our technical department. TO ACCESS: press the MODE button on the SETTING DATA submenu **TO EXIT:** press the **RES** button LANGUAGE SELECTION (default=ITALIANO) It is possible to select up to 6 languages: ITALIAN, ENGLISH, FRENCH, GERMAN, SPANISH, TO BE DEFINED **DISPLAY DEGREES (default=CENTIGRADE)** It allows the user to select whether the temperature is to be displayed in Celsius or Fahrenheit degrees. MAXIMUM SEALING TIME (SECONDS, default = 0.0) Sealing time check. It allows the maximum time of the sealing command to be set. If the sealing command lasts longer than this value, the thermoregulator goes in alarm condition F085. For applications with a sealing command that is always high, this parameter must be set to 0. TEMPERATURE GRADIENT FOR BALANCE (DEGREES/10 SECONDS, default = 4) It shows the maximum temperature cooling down speed expressed in degrees/10 seconds above which the balance is not enabled and warning 38 appears. Increasing this parameter may result in a loss of accuracy. BAND TO GROUND (default = 20%); It can be changed Soft V3.0(ground current=1000ma),Soft V3.1(1000ma),Soft V3.2(1000ma),Soft V3.3(20%) WARN TIME = (SECONDS, default = 3) In the case of warning the thermoregulator signals the failure without going to an alarm condition and stopping. The message is displayed for the seconds specified by this parameter. If this parameter = 0 the message is not displayed, if this parameter is maximum value = 10 the message is dispayed till to reset. SET PAGE1 TEMP. (default = 0) It allows the sealing temperature to be changed directly on the main page using the ARROW UP and ARROW DOWN buttons SET TEMP.END SEAL (default = 0) 1=Latch the temperature at the end of sealing APPENDIX C1 – PRIORITY SETTING DATA managed directly on the MAIN MENU (see par.5.5.4 parameters pages) **PREHEAT TEMPERATURE (default = 100)** It allows to set pre-heat temperature (we suggest to set 40-50 degree less than the seal temperature).

SEAL TEMPERATURE (default = 150)

It allows to set the seal temperature

INCREASE SEALING (default = 0)

It allow to compensate the decrease of temperature caused by the large of the bag to seal, less than 80% of the active zone (zone in the middle of the sealing band not copper plated) INCREASE SEALING is the total increase of the sealing temperature in degree.

TECHNICAL NOTE: the increase of temperature happens:

1)In impulse sealing on the down trigger of the seal command

2)In continuos sealing on the up trigger of the pre-heat command when seal command is on. **INCREASE NR (default = 0)**

It's the number of sealing necessary to obtain the total increase of sealing temperature INCREASE SEALING

RECOVERY TIME (default = 0)

It's the time in seconds necessary to reset the initial condition of sealing temperature.

APPENDIX D – LIST OF ALARMS AND MESSAGES (CAUSES – REMEDIES)

NOTE – To reset any alarm raise the RESET command from the interface and press the **RESET / MODE** button

NOTE – When in the alarm condition the RED LED lights up; the alarm number can be deducted from the green and red LED blinking: **ALARM NO.=NO. OF GREEN LED IMPULSES x 10 + NO. OF RED LED IMPULSES**

NOTE – When in the warning condition the YELLOW LED lights up; the warning number can be deducted from the green and red LED blinking: WARNING NO.=NO. OF GREEN LED IMPULSES x 10 + NO. OF RED LED IMPULSES

NOTE – Any warning is displayed for the second set in the setting data WARN TIME

ALARM	DESCRIPTION	REMEDY
FAULT A	thermoregulator completely OFF plus display completely OFF	Check the power supply; power supply unit faulty; contact the supplier
FAULT C	THERMOREGULATOR WITH LED OPERATING AND DISPLAY ON SHOWING "3E SRL + THERMOSALD"	Check the display connection cable
F001	EEPROM WRITING INTERRUPTED	Switch the equipment OFF and then ON; then contact the supplier
F002	EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESS	Switch the equipment OFF and then ON; then contact the supplier
F003	EEPROM WRITING WITH FAULTY EEPROM	Switch the equipment OFF and then ON; then contact the supplier
F004	INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM	Switch the equipment OFF and then ON; then contact the supplier
F006	PANEL FLASH EEPROM WRING	Switch the equipment OFF and then ON; then contact the supplier
F007	A/D CONVERTER –CONVERTER WRITING ERROR	Switch the equipment OFF and then ON; then contact the supplier
F008	INTERNAL I2C-X TRANSMISSION	Switch the equipment OFF and then ON
F009	DO NOT USE	
F010	A/D CONVERTER –CHANNEL SELECTION ERROR	Switch the equipment OFF and then ON; then contact the

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 45 of: 56

		supplier
F011	COPROCESSOR SELECTOR ON WITH	Coprocessor card problems;
	COPRO CARD NOT ACTIVE OR SEL.	perform a Master Reset and
	COPRO OFF WITH COPRO CARD ACT.	contact the supplier
F012	INTERNAL BUS CARD TRANSMISSION	Switch the equipment OFF and
		then ON; then check the
		parameters
F013	INTERNAL COPROCESSOR CARD	Switch the equipment OFF and
	TRANSMISSION	then ON; then check the
		parameters
F019	RS485 MASTER - CHECKSUM ERROR	Check checksum selection on the
1010		Master and Slave
F020	RS485 SLAVE - CHECKSUM ERROR	Check checksum selection on the
1 020		Master and Slave
F021	RS485 SLAVE - OE OVERRUN ERROR	
FUZI	R5465 SLAVE - DE OVERRUN ERROR	Data have arrived before finishing
F000		reading the previous ones
F022	RS485 SLAVE - FERR FRAME ERROR	Stop bit has not arrived
F023	RS485 MASTER – NO REPLY FROM	After a call of the Master the
	SLAVE	called Slave does not reply
F024	RS485 SLAVE – TOO MUCH DATA	The Master has asked the Slave
	REQUESTED BY THE MASTER OR	for too much data or issued an
	INCORRECT DATA ADDRESS	address that is not enabled
F025	RS485 SLAVE - BUFFER FULL	The buffer of the slave is full
		because too much data have
		been requested or arrived or
		transmissions are too frequent
F026	RS485 MASTER - OE OVERRUN ERROR	Data have arrived before finishing
		reading the previous ones
F027	RS485 MASTER - FERR FRAME ERROR	Stop bit has not arrived
F028	RS485 MASTER – TOO MUCH DATA	The Slave has asked the Master
1 020	REQUESTED BY THE SLAVE OR	for too much data or issued an
	INCORRECT ADDRESS	address that is not enabled
F029	RS485 MASTER - BUFFER FULL	The buffer of the Master is full
1023		because too much data have
F000		arrived
F032	WARNING WAITING POWER DURING	Switch power on
5000		
F033	WARNING: no VOLTAGE IN THE POWER	Check the CN1/L1,L2 power
	TRANSFORMER OR BAND NOT	supply, the power transformer
	CONNECTED	circuit, check connection of the
		power cables on the band.
F034	DO NOT USE	
F035	WARNING – CALIBRATION REQUEST	It is used in the RS485 remote
	STATUS	control
F036	WARNING - STATUS OF CALIBRATION	It is used in the RS485 remote
	IN PROGRESS	control to check the end of
		calibration
F037	EXTERNAL TEMPERATURE PROBE NOT	Check temperature probe
	ALD ISX – IPX – INSTALLATION AND USER MANUAL	Rev.: 8
Code: 3ES1	00_MDU_V4EN Page: 46 of: 56	Date: 08/07/2013

	ACTIVE	connection or TEMPERATURE
E020		PROBE Enabling machine data
F038	WARNING – Waiting for machine to cool	To perform a calibration
	down upon calibration request	procedure it is necessary to wait
		until the sealing bar reaches a
F039		stable temperature. No power for the first sealing
F039 F041	WARNING – Sealing out of range DEFAULT HARDWARE DATA RAM	Switch the equipment OFF and
FU41	CONTROL REAL TIME CORRUPTED	then ON; then contact the
		supplier
F046	NO CURRENT SIGNAL	Check CT connection, band
1 0 - 0	WITH VERY LOW CURRENT ALSO CT	power cable and CN1/L1-L2
	SIGNAL REVERSED	connections.
F047	CT SIGNAL REVERSED	Reverse CT connection
1041		Attention at connection CN6/4-5
		And not CN6/5-6
F048	PREHEAT POTENTIOMETER NOT	Check preheat potentiometer
	CONNECTED OR CABLES	connections
	INTERRUPTED	
F049	SEALING POTENTIOMETER NOT	Check sealing potentiometer
	CONNECTED OR CABLES	connections
	INTERRUPTED	
F051	WIPER-IGROSS	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F052	WIPER-VGROSS	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F053	WIPER-IFINE	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F054	WIPER-VFINE	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F059	PERIOD OF MAIN NET OUT OF RANGE	Switch the equipment OFF and
F 000	(from V4.2)	then ON
F060	RESET WITH CALIBRATION IN	Repeat calibration
F061	PROGRESS IGROSS BALANCE NOT SUCCESSFUL	Repeat calibration
F062	VGROSS BALANCE NOT SUCCESSFUL	Verify if Band +/- Ref connected
1 002		together; Verify if voltage power
		transf. is right; Repeat calibration
F063	IFINE BALANCE NOT SUCCESSFUL	Repeat calibration
F064	VFINE BALANCE NOT SUCCESSFUL	Repeat calibration
F065	SUPERFINE BALANCE NOT	Repeat calibration
1 000	SUCCESSFUL	
F066		Verify connection power
THEDMOO		
F066 THERMOS	WARNING: SYNCHRONISM DUE TO MAINS FREQUENCY OSCILLATION - ALD ISX – IPX – INSTALLATION AND USER MANUAL	Verify connection power transformer and Main Frequency Rev.: 8

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 47 of: 56Date: 08/07/2013

	MAINS SYNCHRONISM INTERFERENCE	
F067	TEMPERATURE>TEMPERATURE	Verify connection sealing bands,
	MAXIMUM FOR 800MS	increase value of max temperat.
F068	TEMPERATURE>TEMPERATURE	Verify connection sealing bands,
	MAXIMUM+10 DEGREE FOR 200MS	increase value of max temperat.
F069	GROUND CURRENT	Check the band on the machine
		or the band connection, probably
		grounded.
		NOTE: the thermoregulator is
		grounded via a ground screw, the
		band wires must therefore be
		disconnected before checking
		using an electrical instrument.
F071	HARDWARE FAULT – ANALOGUE +/–15V	Reset the equipment; if the
	BREAKAGE	problem persists, contact the
		supplier
F072	HARDWARE FAULT – ANALOGUE +/-5V	Reset the equipment; if the
	BREAKAGE	problem persists, contact the
		supplier
F073	HARDWARE FAULT – REFERENCE +5V	Reset the equipment; if the
	BREAKAGE	problem persists, contact the
		supplier
F074	INTERNAL TEMPERATURE PROBE –	Switch the equipment OFF; if the
	HEAT SINK TEMPERATURE TOO HIGH	problem persists, contact the
		supplier
F075	WARNING INTERRUPT FIRE BLOCK	Verify connection power
		transformer and Main Frequency
F076	IREAD TOO HIGH	Check if there is a short circuit on
		the bands
F077	MANUAL CMD FROM THE PANEL NOT	Remove the preheat and sealing
	ACTIVE DUE TO PREHEAT OR SEALING	before giving the command
	FROM OUTSIDE	
F078	EQUIPMENT NOT CALIBRATED	Perform the automatic calibration
-		procedure without giving the
		preheat or sealing command
F079	EMERGENCY CIRCUIT FAULT	Check the power contactor, check
		the emergency chain
F080	BACK FIRE TIMER CONTROL	Reset the equipment; if the
		problem persists, contact the
		supplier
F081	HARDWARE FAULT – CHECKSUM	Inconsistent data have been
	ALARM READING EEPROM	found on eeprom, proceed
		carefully
		Press RESET/MODE, check
		MACHINE DATA, SETTING
		DATA and TEMPERATURES set.
		Contact the supplier
F082	phase displacement between syncronism	Make sure the two power
THERMOS	SALD ISX – IPX – INSTALLATION AND USER MANUAL	Rev.: 8

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 48 of: 56Date: 08/07/2013

	(CN5) and power supply (CN1) – only primary model	supplies are in phase (pay attention to the phase- phase/phase-neutral phase displacement)
F083	REFERENCE CABLES REVERSED WITH RESPECT TO THE POWER CABLES Supply -15V internal	Check the reversed reference cables: CN1/3 corresponds to CN6/1 CN1/4 corresponds to CN6/2
F085	SEALING TIME HIGHER THAN THE SEALING TIME MACHINE DATA	Check the sealing time on the SEALING TIME MACHINE DATA; the sealing time control can be excluded by setting the SEALING TIME MACHINE DATA = 0
F089	BREAK OF A BAND IN CASE OF BANDS CONNECTED IN PARALLEL	Check the bands
F090	SHORT CIRCUIT BETWEEN THE BANDS OR BETWEEN THE BANDS AND GROUND	Check the bands, check power cabling between the thermoregulator and bands Attention at connection CN6/4-5 And not CN6/5-6
F091	I2T CURRENT TOO HIGH ALARM	Check the band on the machine or the band connections. Power delivered too high Attention at connection CN6/4-5 And not CN6/5-6
F092	POWER COMPONENT FAULTY	Reset the equipment; if the problem persists, contact the manufacturer
F093	NO CURRENT ON THE BAND USED FOR SEALING	Check the power transformer, check for any interruption of the band, check for any interruption of the power cables
F094	REFERENCE CABLE INTERRUPTION	Check the reference cables (CN6/1 - CN6/2)
F095	NO MAINS SYNCHRONISM – NOT ACTIVE IN THE ISX-IPX MODELS	Internal hardware problem. Contact the manufacturer
F096	V-I TOO HIGH - NOT ACTIVE IN THE ISX- IPX MODELS	Saturation on the voltage circuit; check the system, probably a band broke if it is connected in parallel
F097	PARTIAL SHORT CIRCUIT BETWEEN THE BANDS	Check the bands on the machine, Probably they are not insulated correctly. If the band is fine and the problem persists, let the machine cool down and calibrate. Pay attention to the machine's

working phases. To remove the problem the PARTIAL SHORT CIRCUIT FACTOR MACHINE DATA can also be raised. F099 ALARM UNKNOWN Contact the manufacturer F100 NOT USED Switch the equipment OFF and then ON; then contact the supplier F101 COPROCESSOR EEPROM WRITING INTERRUPTED Switch the equipment OFF and then ON; then contact the supplier F102 COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESS Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING WITH FAULTY EEPROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F110 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F113 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F133 COPROCESSOR EXTERNAL TEMPERATURE PROBE<			
Problem the PARTIAL SHORT CIRCUIT FACTOR MACHINE DATA can also be raised.F099ALARM UNKNOWNContact the manufacturerF100NOT USEDCOPROCESSOR EEPROM WRITING INTERRUPTEDSwitch the equipment OFF and then ON; then contact the supplierF102COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESSSwitch the equipment OFF and then ON; then contact the supplierF103COPROCESSOR EEPROM WRITING WITH FAULTY EEPROMSwitch the equipment OFF and then ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER - CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER - CONVERTER WRITING ERRORSwitch the equipment OFF and then ONF109DO NOT USEF110COPROCESSOR A/D CONVERTER - CONVECTEDSwitch the equipment OFF and then ONF110COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDSwitch the equipment OFF and then ON; then contact the supplierF134DO NOT USECheck the temperature probe connection on the bandF138WARNING – WAITING FOR MACHINE TO COOL DOWNCheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine dataF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a sta			behaviour in the subsequent
CIRCUIT FACTOR MACHINE DATA can also be raised. F099 ALARM UNKNOWN Contact the manufacturer F100 NOT USED Switch the equipment OFF and then ON; then contact the supplier F101 COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESS Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING WITH FAULTY EEPROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EOFROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F110 COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Switch the equipment OFF and then ON; then contact the supplity, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE F137 F138 WARNING – WAITING FOR MACHINE TO COOL DOWN Check the t			
DATA can also be raised.F099ALARM UNKNOWNContact the manufacturerF100NOT USEDCORROCESSOR EEPROM WRITINGSwitch the equipment OFF and then ON; then contact the supplierF102COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESSSwitch the equipment OFF and then ON; then contact the supplierF103COPROCESSOR EEPROM WRITING WITH FAULTY EEPROMSwitch the equipment OFF and then ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER - COPROCESSOR A/D CONVERTER - CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER - CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF109DO NOT USESwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR A/D CONVERTER - CONNECTEDSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supplierF134DO NOT USEFF135COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or the bandF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing machine data			problem the PARTIAL SHORT
F099 ALARM UNKNOWN Contact the manufacturer F100 NOT USED Switch the equipment OFF and then ON; then contact the supplier F101 COPROCESSOR EEPROM WRITING Switch the equipment OFF and then ON; then contact the supplier F102 COPROCESSOR EEPROM WRITING Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION Switch the equipment OFF and then ON F109 DO NOT USE Switch the equipment OFF and then ON F110 COPROCESSOR A/D CONVERTER – CONVERTER – CONVECESOR Switch the equipment OFF and then ON F113 COPROCESSOR WARNING - NO Check the CN1/L1,L2 power supplier F133 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR F134 DO NOT USE F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE			CIRCUIT FACTOR MACHINE
F099 ALARM UNKNOWN Contact the manufacturer F100 NOT USED Switch the equipment OFF and then ON; then contact the supplier F101 COPROCESSOR EEPROM WRITING Switch the equipment OFF and then ON; then contact the supplier F102 COPROCESSOR EEPROM WRITING Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION Switch the equipment OFF and then ON F109 DO NOT USE Switch the equipment OFF and then ON F110 COPROCESSOR A/D CONVERTER – CONVERTER – CONVECESOR Switch the equipment OFF and then ON F113 COPROCESSOR WARNING - NO Check the CN1/L1,L2 power supplier F133 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR F134 DO NOT USE F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE			DATA can also be raised.
F100 NOT USED F101 COPROCESSOR EEPROM WRITING INTERRUPTED Switch the equipment OFF and then ON; then contact the supplier F102 COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESS Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING WITH FAULTY EEPROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION COPROCESSOR Switch the equipment OFF and then ON; then contact the supplier F109 DO NOT USE Switch the equipment OFF and then ON; then contact the supplier F110 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F133 COPROCESSOR MARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Check the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine data F138 WARN	F099	ALARM UNKNOWN	
F101 COPROCESSOR EEPROM WRITING INTERRUPTED Switch the equipment OFF and then ON; then contact the supplier F102 COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESS Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING WITH FAULTY EEPROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F110 COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Switch the equipment OFF and then ON; then contact the supplier F133 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is neceessary to wait until the sealing bar reaches a stabl			
INTERRUPTEDthen ON; then contact the supplierF102COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESSSwitch the equipment OFF and then ON; then contact the supplierF103COPROCESSOR EEPROM WRITING WITH FAULTY EEPROMSwitch the equipment OFF and then ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER - COPROCESSOR A/D CONVERTER - CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER - CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF109DO NOT USESwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine dataF138WARNING - WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			Switch the equipment OFF and
F102COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESSSwitch the equipment OFF and then ON; then contact the supplierF103COPROCESSOR EEPROM WRITING WITH FAULTY EEPROMSwitch the equipment OFF and then ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER - COPROCESSOR A/D CONVERTER - CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL 12C-X TRANSMISSION COPROCESSOR A/D CONVERTER - COPROCESSOR A/D CONVERTER - CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF109DO NOT USEFF110COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDSwitch the equipment OFF and then ON; then contact the supplierF134DO NOT USECheck the tenthe contact the supplierF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine dataF138WARNING - WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	1 101		
F102 COPROCESSOR EEPROM WRITING WITH PREVIOUS OPERATION IN PROGRESS Switch the equipment OFF and then ON; then contact the supplier F103 COPROCESSOR EEPROM WRITING WITH FAULTY EEPROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION COPROCESSOR Switch the equipment OFF and then ON F109 DO NOT USE Switch the equipment OFF and then ON F110 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON F113 COPROCESSOR MARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Check the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE E F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
WITH PREVIOUS OPERATION IN PROGRESSthen ON; then contact the supplierF103COPROCESSOR EEPROM WRITING WITH FAULTY EEPROMSwitch the equipment OFF and then ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER - CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ON; then contact the supplierF109DO NOT USESwitch the equipment OFF and then ONF110COPROCESSOR A/D CONVERTER - CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection or the bandF134DO NOT USECheck the temperature probe connection or COPROCESSORF138WARNING – WAITING FOR MACHINE TO COOL DOWNCheck the temperature probe connection procedure it is necessary to wait until the sealing bar reaches a stable temperature.	F102		
PROGRESSsupplierF103COPROCESSOR EEPROM WRITING WITH FAULTY EEPROMSwitch the equipment OFF and then ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSOR A/D CONVERTER – CORNOCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF109DO NOT USESwitch the equipment OFF and 	F102		
F103 COPROCESSOR EEPROM WRITING WITH FAULTY EEPROM Switch the equipment OFF and then ON; then contact the supplier F104 COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROM Switch the equipment OFF and then ON; then contact the supplier F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION Switch the equipment OFF and then ON F109 DO NOT USE Switch the equipment OFF and then ON F110 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F133 COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Check the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE Check the temperature probe connection or COPROCESSOR F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
WITH FAULTY EEPROMthen ON; then contact the supplierF104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USEF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF133COPROCESSOR MARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supplierF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
F104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ON; then contact the supplierF109DO NOT USEFF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supplierF134DO NOT USECheck the connection on the bandF134DO NOT USECheck the temperature probe connection or COPROCESSORF138WARNING – WAITING FOR MACHINE TO 	F103		
F104COPROCESSOR INDEX CORRUPTED SOFWARE STRUCTURE READ-WRITE EEPROMSwitch the equipment OFF and then ON; then contact the supplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ON; then contact the supplierF109DO NOT USEF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.		WITH FAULTY EEPROM	then ON; then contact the
SOFWARE STRUCTURE READ-WRITE EEPROMthen ON; then contact the supplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USEFF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supplierF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR to power cable connection on the bandF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			supplier
SOFWARE STRUCTURE READ-WRITE EEPROMthen ON; then contact the supplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USEFF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ONF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supplierF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR to power cable connection on the bandF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	F104	COPROCESSOR INDEX CORRUPTED	
EEPROMsupplierF107COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERRORSwitch the equipment OFF and then ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USESwitch the equipment OFF and then ONF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USECheck the temperature probe connection or COPROCESSORF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSORF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.		SOFWARE STRUCTURE READ-WRITE	
F107 COPROCESSOR A/D CONVERTER – CONVERTER WRITING ERROR Switch the equipment OFF and then ON; then contact the supplier F108 INTERNAL I2C-X TRANSMISSION COPROCESSOR Switch the equipment OFF and then ON F109 DO NOT USE Switch the equipment OFF and then ON F110 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F133 COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Check the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE E F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
CONVERTER WRITING ERRORthen ON; then contact the supplierF108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USE	F107	-	
F108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USESwitch the equipment OFF and then ONF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	1 107		
F108INTERNAL I2C-X TRANSMISSION COPROCESSORSwitch the equipment OFF and then ONF109DO NOT USEF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USECoprocessor EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
COPROCESSORthen ONF109DO NOT USEF110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	E 400		
F109 DO NOT USE F110 COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERROR Switch the equipment OFF and then ON; then contact the supplier F133 COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTED Check the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the band F134 DO NOT USE Coprocessor EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVE F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	F108		
F110COPROCESSOR A/D CONVERTER – CHANNEL SELECTION ERRORSwitch the equipment OFF and then ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USECheck the temperature probe connection or COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			then ON
CHANNEL SELECTION ERRORthen ON; then contact the supplierF133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR Enabling machine dataF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
F133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	F110		
F133COPROCESSOR WARNING - NO VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDCheck the CN1/L1,L2 power supply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.		CHANNEL SELECTION ERROR	then ON; then contact the
VOLTAGE IN THE POWER TRANSFORMER OR BAND NOT CONNECTEDsupply, check the power transformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			supplier
TRANSFORMER OR BAND NOT CONNECTEDtransformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	F133	COPROCESSOR WARNING - NO	Check the CN1/L1,L2 power
TRANSFORMER OR BAND NOT CONNECTEDtransformer circuit, check the power cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.		VOLTAGE IN THE POWER	supply, check the power
CONNECTEDpower cable connection on the bandF134DO NOT USEF137COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVECheck the temperature probe connection or COPROCESSOR TEMPERATURE PROBE NOT ACTIVEF138WARNING – WAITING FOR MACHINE TO COOL DOWNTo perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.		TRANSFORMER OR BAND NOT	
F134 DO NOT USE band F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine data F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			-
F134 DO NOT USE F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine data F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
F137 COPROCESSOR EXTERNAL TEMPERATURE PROBE NOT ACTIVE Check the temperature probe connection or COPROCESSOR TEMPERATURE PROBE Enabling machine data F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	F134	DO NOT LISE	
TEMPERATURE PROBE NOT ACTIVE connection or COPROCESSOR TEMPERATURE PROBE Enabling machine data F138 WARNING – WAITING FOR MACHINE TO To perform a calibration COOL DOWN procedure it is necessary to wait until the sealing bar reaches a stable temperature. Stable temperature.			Check the temperature probe
F138 WARNING – WAITING FOR MACHINE TO COOL DOWN Temperature F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.	1137		
Enabling machine data F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.		TEMPERATURE PRODE NOT ACTIVE	
F138 WARNING – WAITING FOR MACHINE TO COOL DOWN To perform a calibration procedure it is necessary to wait until the sealing bar reaches a stable temperature.			
COOL DOWN procedure it is necessary to wait until the sealing bar reaches a stable temperature.	-		
until the sealing bar reaches a stable temperature.	F138		•
stable temperature.		COOL DOWN	
			until the sealing bar reaches a
			•
F143 BASIC TEMPERATURE <> Verify CT cables of coprocessor	F143	BASIC TEMPERATURE <>	Verify CT cables of coprocessor
COPROCESSOR TEMPERATURE and processor; possible			
connection defective			
F144 BASIC TEMPERATURE > Proceed carefully; calibrate,	F144	BASIC TEMPERATURE >	
COPROCESSOR TEMPERATURE+16 check the processor open CT	• • • •		•
(FOR 5 IMPULSE) cables; contact the supplier			capies, contact the supplier

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 50 of: 56Date: 08/07/2013

F145		Dragged corofully collibrate
F145	COPROCESSOR TEMPERATURE >	Proceed carefully; calibrate,
	BASIC TEMPERATURE+16	check the coprocessor open CT
	(FOR 5 IMPULSE)	cables; contact the supplier
F146	COPROCESSOR - NO CURRENT SIGNAL	Check the CT connections and
		band power cable connections
F147	COPROCESSOR CT SIGNAL REVERSED	Reverse the CT connection
F151	COPROCESSOR WIPER-IGROSS	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F152	COPROCESSOR WIPER-VGROSS	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F153	COPROCESSOR WIPER-IFINE	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F154	COPROCESSOR WIPER-VFINE	Switch the equipment OFF and
		then ON; if the problem persists,
		contact the supplier
F0159	PERIOD OF MAIN NET OUT OF RANGE	Switch the equipment OFF and
10100	(from V4.2)	then ON
F160	COPROCESSOR RESET WITH	Repeat calibration
1 100	CALIBRATION IN PROGRESS	Repeat calibration
F161	COPROCESSOR IGROSS BALANCE NOT	Repeat calibration
1 101	SUCCESSFUL	
F162	COPROCESSOR VGROSS BALANCE	Repeat calibration
1 102	NOT SUCCESSFUL	
F163	COPROCESSOR IFINE BALANCE NOT	Repeat calibration
1 103	SUCCESSFUL	
F164	COPROCESSOR VFINE BALANCE NOT	Repeat calibration
1 104	SUCCESSFUL	
F165	COPROCESSOR SUPERFINE BALANCE	Repeat calibration
1 105	NOT SUCCESSFUL	Repeat calibration
F166	COPROCESSOR WARNING:	Verify connection power
FIOO	SYNCHRONISM DUE TO MAINS	
	FREQUENCY OSCILLATION -	transformer and Main Frequency
F167	MAINS SYNCHRONISM INTERFERENCE	Dropped parefully: sheet the
F167	COPROCESSOR TEMPERATURE > MAXIMUM TEMPERATURE	Proceed carefully; check the
		preheat and sealing
	(FOR 600MS)	temperatures; check the
		maximum temperature
		parameter; contact the supplier,
		check the coprocessor open CT
E400		cables
F168	COPROCESSOR TEMPERATURE >	Proceed carefully; check the
	BASIC TEMPERATURE+10	preheat and sealing
	(FOR 100MS)	temperatures; check the
		maximum temperature
		parameter; contact the supplier,
TUERMOO	ALD ISX - IPX - INSTALLATION AND LISER MANILIAL	Rev: 8

THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 51 of: 56Date: 08/07/2013

		check the coprocessor open CT cables
F169	COPROCESSOR GROUND CURRENT	Check the band on the machine or the band connection, probably grounded. NOTE: the thermoregulator is grounded via a ground screw, the band wires must therefore be disconnected before checking using an electrical instrument.
F170	COPROCESSOR READ=0 WITH PHASE OPEN AND HIGH CURRENT	Current passes without any reading enable signal; contact the supplier
F171	COPROCESSOR HARDWARE FAULT – ANALOGUE +/–15V BREAKAGE	Reset the equipment; if the problem persists, contact the supplier
F172	COPROCESSOR HARDWARE FAULT – ANALOGUE +/-5V BREAKAGE	Reset the equipment; if the problem persists, contact the supplier
F173	COPROCESSOR HARDWARE FAULT – REFERENCE +5V BREAKAGE	Reset the equipment; if the problem persists, contact the supplier
F174	COPROCESSOR INTERNAL TEMPERATURE PROBE – HEAT SINK TEMPERATURE TOO HIGH	Switch the equipment OFF; if the problem persists, contact the supplier
F175	COPROCESSOR WARNING INTERRUPT FIRE BLOCK	Verify connection power transformer and Main Frequency
F176	COPROCESSOR IREAD TOO HIGH	Check if there is a short circuit on the bands
F178	COPROCESSOR NOT CALIBRATED	Calibrate
F179	COPROCESSOR DON'T RECEIVE FROM MASTER INTERNAL TRASMISSION DATA BUS	Reset the equipment; if the problem persists, contact the supplier
F180	COPROCESSOR READ ENABLE NOT RECEIVED	Reset the equipment; if the problem persists, contact the supplier
F181	COPROCESSOR HARDWARE FAULT – CHECKSUM ALARM READING EEPROM	Proceed carefully; Press RESET/MODE, check MACHINE DATA, SETTING DATA and TEMPERATURES set. Contact the supplier
F182	COPROCESSOR AND BASIC TEMPERATURE ENABLING INCONSISTENT	Make sure both temperature probes are connected or disconnected; then perform a MASTER RESET to acquire
F183	COPROCESSOR REFERENCE CABLES REVERSED WITH RESPECT TO THE POWER CABLES	Check the reversed reference cables: CN1/3 corresponds to CN6/1


THERMOSALD ISX - IPX - INSTALLATION AND USER MANUALRev.: 8Code: 3ES100_MDU_V4ENPage: 52 of: 56Date: 08/07/2013

		CN1/4 corresponds to CN6/2
F184	COPROCESSOR SEALING COMMAND INCONSISTENT WITH BASIC (INTERNAL CONTROL)	Switch the equipment OFF and then ON; if the problem persists, contact the supplier (Coprocessor does not receive CO_SALD_IN_ACT from base)
F0185	SEALING TIME HIGHER THAN THE SEALING TIME MACHINE DATA	Check the sealing time on the SEALING TIME MACHINE DATA; the sealing time control can be excluded by setting the SEALING TIME MACHINE DATA = 0
F190	COPROCESSOR SHORT CIRCUIT BETWEEN THE BANDS OR BETWEEN THE BANDS AND GROUND	Check the bands, check the power cabling between the thermoregulator and bands
F191	COPROCESSOR I2T CURRENT TOO HIGH ALARM	Check the band on the machine or the band connections. Power delivered too high
F193	COPROCESSOR NO CURRENT ON THE BAND USED FOR SEALING	Check the power transformer, check for any interruption of the band, check for any interruption of the power cables
F194	COPROCESSOR REFERENCE CABLE INTERRUPTION	Check for any interruptions in the reference cables (CN6/1 - CN6/2)
F195	COPROCESSOR NO MAINS SYNCHRONISM, NOT ACTIVE IN THE ISX-IPX MODEL	Internal hardware problem. Contact the manufacturer
F196	COPROCESSOR V-I TOO HIGH, NOT ACTIVE IN THE ISX-IPX MODEL	Saturation on the voltage circuit; check the system, probably a band broke if it is connected in parallel
F197	COPROCESSOR PARTIAL SHORT CIRCUIT BETWEEN THE BANDS	Check the bands on the machine, Probably they are not insulated correctly. If the band is fine and the problem persists, let the machine cool down and calibrate. Pay attention to the machine's behaviour in the subsequent working phases. To remove the problem the PARTIAL SHORT CIRCUIT FACTOR MACHINE DATA can also be raised.
F199	COPROCESSOR ALARM UNKNOWN	Contact the supplier

.


APPENDIX E – MECHANICAL DIMENSIONS

DIGITAL PANEL: 96x48 – REAR DIMENSIONS: 90.5x44.5 DEPTH = 73mm + Connector 52mm



NOTE: with IP65 protection, code 3ES108Z=IP65, do drilling template 94mm x 47mm, Maximum external size 102mm x 54mm

THERMOREGULATOR DIMENSIONS 100 x 120 (VIEW FROM TOP) HEIGHT = 135mm (3 Levels model) / 155mm (4 Levels model) / 175mm (5 Levels model)



THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 54 of: 56

APPENDIX F - TABLE OF BANDS

TABLE OF THE CHAMFERED BANDS IN SPECIAL ALLOY (Band extension 50PPM, 0.05mm/metre per degree – 5mm/metre per 100 degrees)

Band Width (mm)	Band Thickness (mm)	Specific Resistance R0 Ω / m
1.5	0.3	1.67
2	0.25	1.59
3	0.1	2.95
3	0.15	1.95
3	0.2	1.50
3	0.25	1.27
4	0.15	1.40
4	0.25	0.96
5	0.2	0.8
5	0.25	0.69
6	0.1	1.6
6	0.2	0.72
8	0.1	1.2
8	0.2	0.51

TABLE OF THE T-SHAPE BANDS IN SPECIAL ALLOY

Band Width (mm)	Band Thickness (mm)	Specific Resistance R0 Ω / m
2.8	0.3	0.9
4	0.3	0.6

TABLE OF THE BEADED ELEMENT BANDS IN SPECIAL ALLOY

Band Width (mm)	Band Thickness (mm)	Specific Resistance R0 Ω / m
4	0.15	1.4
4	0.25	0.9
6	0.15	0.99
6	0.25	0.6

TABLE OF THE CONCAVE BANDS IN SPECIAL ALLOY

Band Width	Band Thickness	Specific Resistance R0
(mm)	(mm)	Ω / m
2.8	0.3	0.9

THERMOSALD ISX - IPX -INSTALLATION AND USER MANUALCode: 3ES100_MDU_V4ENPage: 55 of: 56

APPENDIX G – COMMISSIONING SHEET

SEALING BANDS WIDTH X THICKNESS	
SEALING BANDS TOTAL LENGTH	
USEFULL LENGTH (TOTAL - COPPER	
TRANSFORMER POWER [VA]	
TRANSFORMER PRIMARY VOLTAGE [V]	
TRANSFORMER SECONDARY VOLT [V]	
THERMOSALD ISX / IPX MODEL	
ORDERED OPTIONS	
PREHEAT TEMPERATURE [°C]	
SEALING TEMPERATURE [°C]	
SEALING TIME [Sec.]	

TABLE OF THE DATA CHANGED DURING COMMISSIONING

(MACHINE DATA, SETTING DATA, COMMISSIONING DATA)	DEFAULT VALUE	NEW VALUE